

Operating manual



WEEE Information

IT

“Attuazione della direttiva 2012/19/UE sui rifiuti di apparecchiature elettriche ed elettroniche (RAEE)”



Il simbolo del cassonetto barrato riportato sull'apparecchiatura o sulla sua confezione indica che il prodotto alla fine della propria vita utile deve essere raccolto separatamente dagli altri rifiuti.

La raccolta differenziata della presente apparecchiatura giunta a fine vita è organizzata e gestita dal produttore.

L'utente che desidera disfarsi dell'apparecchiatura dovrà quindi contattare il produttore per ricevere indicazioni sul sistema da quest'ultimo adottato per consentire la raccolta separata dell'apparecchiatura giunta a fine vita.

L'adeguata raccolta differenziata per l'avvio successivo dell'apparecchiatura dismessa al riciclaggio, al trattamento e allo smaltimento ambientalmente compatibile contribuisce ad evitare possibili effetti negativi sull'ambiente e sulla salute e favorisce il reimpiego e/o riciclo dei materiali di cui è composta l'apparecchiatura.

EN

“Implementation of Directive 2012/19/EU on waste electrical and electronic equipment (WEEE)”



The symbol showing a crossed-out wheeled bin on equipment or its packaging indicates that the product must be collected separately from other waste at the end of its useful life.

The manufacturer is responsible for organising and managing the separate collection of this piece of equipment at the end of its useful life.

Users wishing to dispose of the equipment must therefore contact the manufacturer to obtain instructions from the same on how to have the equipment collected separately at the end of its useful life.

By collecting the disused equipment separately, it can be recycled, treated or disposed of in an environmentally friendly manner, thus helping to prevent the environment and public health from being affected negatively and enabling reuse and/or recycling of the materials forming the same equipment.

DE

„Umsetzung der Richtlinie 2012/19/UE über Elektro- und Elektronik-Altgeräte (EEA)“



Das Symbol der durchgekreuzten Mülltonne auf dem Gerät oder der Geräteverpackung weist darauf hin, dass Sie das Produkt am Ende seines Lebenszyklus separat entsorgen müssen.

Die Getrenntsammlung dieses Geräts an seinem Lebenszyklusende wird vom Hersteller organisiert und besorgt.

Der Nutzer, der das Gerät entsorgen möchte, muss sich daher an den Hersteller wenden, um Auskunft über seine Vorgehensweise zur Getrenntsammlung des Geräts an dessen Lebenszyklusende zu erhalten.

Die entsprechende Getrenntsammlung für die anschließende Zuführung des Altgeräts zum Recycling, zur Wiederaufbereitung und zur umweltverträglichen Entsorgung trägt dazu bei, negative Auswirkungen auf die Umwelt und die Gesundheit zu unterbinden und begünstigt die Wiederverwendung und/oder das Recycling von Werkstoffen, aus denen das Gerät besteht.

FR

“Transposition de la Directive 2012/19/UE relative aux déchets d'équipements électriques et électroniques (RAEE)”



Le pictogramme de la poubelle barrée, figurant sur l'équipement ou sur son emballage, indique que le produit en fin de vie doit être traité séparément des autres déchets.

Le ramassage sélectif de cet équipement en fin de vie est organisé et géré par le constructeur.

Tout utilisateur qui souhaiterait se débarrasser de l'équipement devra donc contacter le constructeur pour obtenir des informations concernant la méthode adoptée pour permettre le ramassage sélectif de l'équipement en fin de vie.

Un ramassage sélectif correct, en vue de l'acheminement de l'équipement vers des opérations de recyclage, de traitement et de mise au rebut respectueuses de l'environnement, contribue à réduire les impacts potentiellement néfastes sur l'environnement et la santé, outre à favoriser la réutilisation des matériaux/composants dont l'équipement est constitué.

GE1029

TIE-BAR STRAIN SENSOR



Main features:

- Direct measurement of surface strain
- Quick and easy non-destructive assembly
- High accuracy and linearity in tension and pressure (like bonded strain gauges)
- Ideal for use on presses, injection-moulding and die-casting machines
- One system for many different tie bar diameters (25...400mm)
- Dynamic applications
- Without amplifier (passive)
- Ideal for online monitoring of clamping force
- Ideal for self-made load cells

Product description

The strain gauge sensor GE1029 measures the surface-strain directly at the mounting location in the same quality as bonded strain gauges. The press-on technology, developed by Gefran Schweiz AG, presses the strain gauges under the stainless protective film so strongly against the surface to be measured that frictional contact occurs.


The sensor does not have to be recalibrated between remove and re-installation. The sensor is mounted using stainless steel straps, is non-destructive, very fast and simple. For each tie-bar diameter outside tolerance of $\pm 2.5\text{mm}$ a different pair of steel straps is required. The sensor can not be overloaded. The GE1029 sensors require a cyclic reset.

Technical Data


Strain gauge type	Foil (GF = 2.0)
Bridge resistance	350Ω
Measuring range	± 1000 µε
Sensitivity tolerance	± 0.2%
Transverse sensitivity	0.9 ± 0.2 %
Accuracy	<± 0,5% FS
Linearity	<± 0,5% FS
Hysteresis	<± 0,2% FS
Repeatability	< 0,1% FS
Supply voltage	5VDC (max. 8VDC)
Supply current	< 15mA
Operating temperature range	-20...+70°C
Storage temperature range	-20...+70°C
Overload capability	indefinite (offset occurs)
Protection class	IP64
Case material	Anodised aluminium
Weight, including cable	200g

Dimensions

Installation requirements	
Press-on torque (M4 screws)	2.0 Nm
Surface installation spot	N7




Application: Self-made load-cell




Dimensions in mm

Electrical Connection

2/4 Bridge




Option C: cable with connector



Option C Connector Pin	Option O open leads	Function
1	red	Strain gauge 1
2	red	Strain gauge 1
3	-	n.a.
4	yellow	Strain gauge 2
5	yellow	Strain gauge 2
6	-	n.a.


Option O: cable with open leads




2x PVC screened cable (standard); 2 x 0.14 mm§; Ø 3.5mm

Electrical Connection

4/4 Bridge



Option C: cable with connector



Option C Connector Pin	Function
1	Excitation +
2	Excitation +
3	Excitation -
4	Signal +
5	Signal -
6	Excitation -

Assembly


These sensors are precision instruments. The devices must be handled with the appropriate care. These instructions must be read and understood by every user.

Preparation


- Oil and other surface impurities as well as paint must be removed from the place of installation.
- The surface roughness of the place of installation has not to be rougher than N7.
- Check the foil of the sensor GE1029 for damage.
- The foil of the sensor GE1029 must be absolutely clean.

Assembly procedure

1.
There are markings on the stainless steel bands.
(The distance between these markings depends on the diameter of the object to be measured)




2.
The stainless steel strips are fixed at the marked position with the individual measuring modules.




3.
Place the sensor around the object to be measured and screw it on carefully.

Do not tighten with final torque yet!


Cables must not be jammed.




4.
Slightly loosen the fixing so that the individual measuring modules can rest perfectly on the circumference of the measuring object.



5.
The contact points must lie exactly in the axial direction on the surface to be measured.



-
6.
Screw the sensors hand-tight.
Torque = 2 Nm
The two measuring modules must be
exactly opposite each other.



The system is now ready to measure.



Attention:

It is important that the screws are checked with the above torque after the machine has warmed up or after two days of operation at the latest.

Maintenance

Inspection

To prevent damage to the film, it should always be checked before using the sensor.
Remove any impurities immediately.

Maintenance

The sensor GE1029 should be checked every 12 months. For maintenance the sensor must be sent to Gefran Schweiz AG.

DU1D

1- CHANNEL MONITOR



Main features:

- Available for all Sensormate sensors (2/4 bridges)
- Direct display of the measured values in $\mu\epsilon$, kN or t
- High accuracy and stable reset
- Automatic reset, external reset and alarm output
- Ideal for control cabinet installation (96x96mm, DIN 43700)
- Battery operation possible (optional) / not rechargeable

Product description

The DU1D Monitor is an industrial signal amplifier and monitor for strain gauges and strain sensors. It has integrated functions for external and internal (automatic) reset. Force measurement on tie bars displays in kN or tons and diameter input. Strain measurement displays in $\mu\epsilon$ (micro strain). Direct switch units and change parameters. The handling is very user-friendly.

Application:


The device DU1D is used in conjunction with tie bar strain-sensors of the Gefran Schweiz AG for the control of the clamping force on presses, injection-moulding and die-casting machines. The ALARM relay allows to stop the machine in case of overload. Ideal to retrofit on existing machines.

Technical Data

Input bridge resistance	350...1000Ω
Signal input range (FS)	0,1...1mV/V
Resolution ADC	16-Bit
Sampling rate	500Hz
Output rate	40Hz
Display refresh	100Hz
Output signal	Display (± 9999 digit, 1 channel)
Noise	≤ 1 digit
Accuracy	<± 0,05% FS
Accuracy of zero point	≤ 1 digit
Linearity	<± 0,5% FS
Alarm reaction time	> 25ms
Reset time	> 200ms
Reset voltage	15...28VDC
Supply voltage	12VDC
Supply current	< 100mA
Inverse polarity protection	Yes
Accidental short-circuit protection	No
Operating temperatur range	0...+65°C
Storage temperatur range	-40...+80°C
Temperatur coefficient at 10°C	< 0,1 (0,05 typical)
Protection class	IP50
EMC	2014/30/EU
Case material	Plastic
Weight	210g


Dimensions

Option: Installation-Housing



Dimensions in mm

Option: Box-Housing




Dimensions in mm

Mounting and installation


Electrical connection

Option: Installation Housing	Function	Option: Box-Housing
Connection pin		Connection M16 x 6-pin
1	Power supply 12VDC	alternative connection
2	GND	alternative connection
3	Reset +	-
4	Reset -	-
5	Alarm switch	-
6	Alarm switch open	-
7	Alarm switch closed	-
8	Strain gauge 1	1
9	Strain gauge 1	2
10	Shield	-
11	Strain gauge 2	4
12	Strain gauge 2	5

Option: Box-Housing



Option: Installation Housing



Operation and control

Faceplate description



△	Decrease chosen value
▽	Increase chosen value
ALARM	Set alarm threshold
DIAM	Set tie-bar diameter
UNIT	Select unit (μE, kN or tons)
RESET	Set measurement to zero
LED's	Indicate actual unit and/or mode
ALARM LED	LED on = alarm out active

Calibration

The monitor is factory calibrated to a cable length of 3m, 5m or 10m.

Attention:

The cable length influences the signal because the supplementary resistors and the cable enter the bridge.

Calibration cycle:

The DU1D monitor should be calibrated every 12 months. For calibration, the DU1D monitor must be sent to Gefran Schweiz AG. With the optionally available strain simulator, the calibration can be carried out at the customer level.

Functions

Unit

µε (micro strain)	Displays the strain measured in µε (1000µm/m)
kN (kilo Newton)	Displays the load in kN (diameter must be set).
tons	Displays the load in tons. (diameter must be set)
T.Force	Displays the value in kN or tons, multiplied by 4 (diameter must be set)
Custom	Displays the value calibrated by the user.

Adjust diameter

For the force calculation in kN or tons the diameter of the cylindrical structure (column) must be set.

Press and hold the “DIAM” button, while adjusting the diameter with the “UP/DOWN” buttons. Then release the “DIAM” button. The diameter value is set now. Check the diameter setting any time by pressing the “DIAM” button.

Alarm setting

- Press and hold the „ALARM“ button and simultaneously set the alarm value with the „UP/DOWN“ buttons. Then release the „Alarm“ button.
-> the alarm is activated.
An alarm value = „0“ causes the alarm to be deactivated.
- Alarm values must be set separately for each unit.
- Alarm values for kN and tons are interdependent. This means that if the setting value is changed to kN, this automatically changes the setting value in tons, corresponding to the conversion „kN? tons“ and vice versa.
-> the alarm values in T. Force are also dependent on it because they only have the kN-value or tone value quadruple.
- The custom alarm setting values „Custom-kN“ and „Custom-tons“ are also interdependent.

Upper and lower limit value of the alarm

The function for changing the operating mode of the alarm from UL to LL and vice versa is available as of software version 3.4.

UL =	Upper limit value
LL =	Lower limit value

Setting the operating mode:

1. The DU1D must be switched off.
2. Press and hold the 'ALARM' -button, then switch on the instrument during this time (respectively plug in the power supply). -> Release the alarm button.
3. One of the two displays appears:
 - UL active: 4 lines appear in the display at the top: - - - -
 - LL active: 4 lines appear in the display at the bottom: _ _ _ _
4. Use the UP or DOWN buttons to select the operating mode.
5. Press the "RESET" button -> The operating mode is stored.


Automatic reset

The DU1D monitor is set to the maximum value of $1000\mu\epsilon$ at the factory. From a strain signal of $30\mu\epsilon$ (cycle start value), the monitor displays values.

As soon as the current value falls below 5% of the maximum value measured in the current cycle, the DU1D monitor carries out a reset (minimum 500ms). For correct measurements, the reset time (= time without load) must be at least 500ms.

Measured value > value of the cycle start	-> Current value is displayed
Measured value < value of the cycle start	-> Display: '0000'

Value of the cycle start in "microStrain, kiloNewton or Tons":	$30\mu\epsilon$
Value of the cycle start in „Custom mode“:	10% of the calibrated value
Minimum display value:	30 Digit



Auto-Reset function ON/OFF:

1. Press and hold UP/DOWN buttons together, press DIAM button and hold.
2. Keep pressing all 3 keys until in the display appears:
 - > "Auto" for Auto-Reset ON
 - > or "OFF" for Auto-Reset OFF

Custom calibration

Set customer-specific maximum value

1. Select on the display "Custom-kN" or "Custom-t".
2. Press the UP and DOWN buttons simultaneously for 5 seconds.

-> Display: "SErO":



3. The machine must be open, i. e. without load, -> then press the „RESET“ button.

-> Display: "LOAd":



4. Now move the machine to full load, -> then press the „RESET“ button.

-> Display: "Set":



5. Set the alarm value with the „UP“ and „DOWN“ buttons.
6. Press the „RESET“ button.
7. The custom calibration is set.

Check software version

1. The DU1D must be switched off.
2. Press the "UNIT" and "UP" button simultaneously.
3. Turn on the device while both buttons are still pressed.
4. The software version of the device is now displayed.

Troubleshooting

Error messages

E01	This message appears if no sensor is connected, or the offset value of the sensor is too large to display the 1000µε.
E02	The measured value is greater than "9999" -> Display is not possible.
E03	The alarm value has been reached. The maximum measured value and "E03" are displayed alternately.
E04	The device is not set to "Custom". Switch to "Custom" and calibrate again.
E99	Incorrect calibration. Turn the unit off and on again. If the message still appears, call to the service of Gefran Schweiz AG.

Maintenance

Servicing

The DU1D monitor should be calibrated every 12 months. For calibration, the DU1D monitor must be sent to Gefran Schweiz AG. With the optionally available strain simulator, the calibration can be carried out at the customer level.

Notes

GEFRAN

GEFRAN spa

via Sebina, 74 - 25050 Provaglio d'Iseo

(BS) - ITALIEN

Tel.: +39 030 9888.1 - Fax: +39 030 9839063

Internet: www.gefran.com

Gefran Schweiz AG

Steigweg 8, - CH-8355 Aadorf, Schweiz

Tel.: +41 52 523 25 00

Fax: +41(0)52-3661884

Internet: www.gefran.com

06-2025